

BOROUGH OF CALDWELL

DEPARTMENT OF PUBLIC WORKS GARAGE

1 Provost Square

- Current Building Use: *DPW vehicle & equipment storage/
DPW personnel workplace*
- Current Overall Condition: *Poor*
- Current Building Issues:

	Urgent -->		Less Urgent		
	1	2	3	4	5
- Needs a new roof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Needs exhaust ventilation repairs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Needs a bathroom renovation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Needs broken window repairs	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>